


I = 31 A

Poles = 4



— Voltage [V] — Power [kW] — Torque [Nm]