


I = 21,6 A Poles = 2



— Voltage [V] — Power [kW] — Torque [Nm]